


ASTM D-412 Specimen Dies

<p style="text-align: center;">D-412-A-IMP</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">#</th> <th style="width: 90%;">Nominal Dimension</th> </tr> </thead> <tbody> <tr><td>A</td><td>5.500</td></tr> <tr><td>B</td><td>1.000</td></tr> <tr><td>C</td><td>.500</td></tr> <tr><td>D</td><td>1.250</td></tr> </tbody> </table>	#	Nominal Dimension	A	5.500	B	1.000	C	.500	D	1.250	<p style="text-align: center;">D-412-B-IMP</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">#</th> <th style="width: 90%;">Nominal Dimension</th> </tr> </thead> <tbody> <tr><td>A</td><td>5.500</td></tr> <tr><td>B</td><td>1.000</td></tr> <tr><td>C</td><td>.250</td></tr> <tr><td>D</td><td>1.250</td></tr> </tbody> </table>	#	Nominal Dimension	A	5.500	B	1.000	C	.250	D	1.250
#	Nominal Dimension																				
A	5.500																				
B	1.000																				
C	.500																				
D	1.250																				
#	Nominal Dimension																				
A	5.500																				
B	1.000																				
C	.250																				
D	1.250																				
<p style="text-align: center;">D-412-C-IMP</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">#</th> <th style="width: 90%;">Nominal Dimension</th> </tr> </thead> <tbody> <tr><td>A</td><td>4.500</td></tr> <tr><td>B</td><td>1.000</td></tr> <tr><td>C</td><td>.250</td></tr> <tr><td>D</td><td>1.250</td></tr> </tbody> </table>	#	Nominal Dimension	A	4.500	B	1.000	C	.250	D	1.250	<p style="text-align: center;">D-412-D-IMP</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">#</th> <th style="width: 90%;">Nominal Dimension</th> </tr> </thead> <tbody> <tr><td>A</td><td>4.000</td></tr> <tr><td>B</td><td>.630</td></tr> <tr><td>C</td><td>.125</td></tr> <tr><td>D</td><td>1.250</td></tr> </tbody> </table>	#	Nominal Dimension	A	4.000	B	.630	C	.125	D	1.250
#	Nominal Dimension																				
A	4.500																				
B	1.000																				
C	.250																				
D	1.250																				
#	Nominal Dimension																				
A	4.000																				
B	.630																				
C	.125																				
D	1.250																				
	<p style="text-align: center;">D-412-F-IMP</p> <table border="1" style="margin-left: auto; margin-right: auto; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;">#</th> <th style="width: 90%;">Nominal Dimension</th> </tr> </thead> <tbody> <tr><td>A</td><td>5.000</td></tr> <tr><td>B</td><td>0.630</td></tr> <tr><td>C</td><td>0.250</td></tr> <tr><td>D</td><td>1.250</td></tr> </tbody> </table> <p style="text-align: center;">*Dimensions are in Inches</p>	#	Nominal Dimension	A	5.000	B	0.630	C	0.250	D	1.250										
#	Nominal Dimension																				
A	5.000																				
B	0.630																				
C	0.250																				
D	1.250																				

Quality Instruments For Your Testing Needs

For more information please contact us at:



WWW.WORLDOFTEST.COM

E-MAIL: INFO@QUALITEST-INC.COM

Qualitest USA LC (US Inquiries)
 3706 N. Ocean Blvd., # 200
 Ft. Lauderdale, FL 33308, USA
 Tel: 1.877.884.TEST Fax: 954.697.8211

Qualitest International Inc. (Canada & overseas inquiries)
 25 Valleywood Dr., Unit 21
 Markham, Ontario L3R 5L9, Canada
 Tel: 905.944.9825 Fax: 905.944.0304